MEMO

SINCE 1950

PO Box 743 1330--12th St. NW Albuquerque, NM 87103 1-505-247-1596

FAX 1-505-247-8364 NM TOLL FREE 1-877-247-1596

e-mail: biz@gormanindustries.com



RE: Fujitsu

Factory recommends that the following items **NOT** be added to their systems.

- Sight Glasses
 - 1. Metering is accomplished in the outdoor unit
 - 2. Refrigerant between the indoor and outdoor units is in saturated gas form
- P-traps(pressure traps)
- Filter Driers
- Valves of any type

NOTE:

• Each refrigerant line(gas and liquid) MUST BE INSULATED SEPARATELY.

Common Installation MISTAKES

- Incorrect wiring
 - 1. Size and/or type
 - 2. Use of splices, wire nuts, etc
 - 3. Incorrect connection (polarity incorrect)
- Refrigerant pipes not insulated properly
 - 1. Not insulated or insulated together
 - 2. Use of any of the items listed above NOT recommended by manufacturer
- Leaks due to improper flares
- Improper condensate drainage
 - 1. Incorrect install of pump
 - (a) Drain pitch, safety circuit, placement, etc.
- Improper lineset selection/installation
 - 1. Lineset caps/plugs not removed before connection
 - 2. Improper lineset size installed